

Komponentliste PIC16F876 baseret automatisk 1,8 til 60 MHz - SWR & Watt meter.

	1	Antal	Modul
Modstande			
47 K ohm		1	SWR-bro
100 ohm		4	SWR-bro
1 K ohm SMD		1	PIC
10 ohm SMD		5	PIC
33 ohm stik i hul		1	PIC
0 ohm SMD		3	PIC
8,2 K ohm		2	SWR-bro
10 K ohm SMD		5	PIC
39 K ohm		2	SWR-bro
3,3 K ohm		1	SWR-bro
Trimme modstand			
4,7 K ohm		1	SWR-bro
10 K ohm		1	PIC
Spoler			
1 mH		1	PIC
10 uH		2	SWR-bro
Kondensator			
10 uF tantal SMD eller E-lyt stik i hul		2	PIC
4,7 pF 200 V		1	SWR-bro
22 nF		6	SWR-bro
100 nF SMD/ en med ber		4/5	PIC
15 pF		2	SWR-bro
22 pF SMD		3	PIC
82 pF		1	SWR-bro
Trimme kondensator			
60 pF keramisk		1	SWR-bro
Diode			
1N5711		2	SWR-bro
1N4001		1	PIC
Regulator			
78L09		1	PIC
7805		1	PIC
PIC-kreds			
PIC16F876		1	PIC
Sokel 28 pin		1	PIC
X-tal			
4 MHz		1	PIC
Ferrite			
FT50-43		1	SWR-bro
Lakket kobbertråd			
0,4 mm længde i cm		50	SWR-bro
Coax			
RG174 længde i cm		7	SWR-bro
Stik			
SO239 eller N		2	SWR-bro
Knapper			
Reset knap.		5	PIC
Display			
2 rækker a 16 car.		1	PIC